

Features:

- Captures and prevents grease from reaching rooftop or other areas.
- Durable and clear plastic container allows for easy visual inspection of grease buildup.
- Separates grease from water.
- >>> Easy to install and easy to use.
- Environmentally friendly. Safe for employees. No chemicals are used.
- >>> Plastic is recyclable.



Maintenance:

Depending on the amount of grease discharged through the fan, the **Terminator 2** should be changed every 30 to 45 days to ensure proper operation.

The new clear canister, constructed of a durable recyclable plastic, assists in your maintenance needs. Any buildup of grease is easily seen during complete visual inspection of the canister on a regular basis.

However, if the **Terminator 2** becomes saturated, grease will no longer be absorbed.



Installation:

Installation of the **Terminator 2** on several models is accomplished by attaching the terminator assembly (extended tubing and **Terminator 2**) to the drain hole in the fan.

For model **LPB** exhaust ventilator, the **Terminator 2** assembly attaches to the drain hole in the bottom of the air diverters. Model **LPB** requires two terminators. The model **VCR** requires one **Terminator 2**.

Once the assembly tubing is installed, it need not be replaced when the **Terminator 2** is replaced.



The LOREN COOK Grease Terminator 2 is designed to "terminate" grease problems generated in most kitchen applications.

When used properly, the multiple-layer, dual-fiber, greasecapture and containment system stops grease from reaching roof tops and other areas.

The **Terminator 2** captures grease in highly purified fibers, separates the grease particles from all moisture, and then repels the moisture.

The unique reverse flow design prevents washout during periods of high humidity and heavy rainfall.

The clear canister, which fastens to the drain of an upblast roof ventilator, absorbs almost eight times it's own weight and is easily installed on COOK model VCR and LPB restaurant roof exhaust ventilators and COOK CP series.



LOREN COOK COMPANY

2015 E. DALE STREET
SPRINGFIELD, MO 65803-4637
417.869.6474
FAX 417.862.3820
lorencook.com